



March 30th, 2015

Addendum No. 1
Re-Roofing Project-Berenda Elementary School
BID No.141503

NOTICE TO ALL VENDORS:

This Addendum is attached to and made a part of the above entitled specifications for Madera Unified School District unified School District with an BID due date of April 2nd, 2015 by 2:00 p.m.

All changes and/or clarifications will appear in bold type and deletions will be struck out within a sentence.

Bid Due Date:

1. ~~April 2nd~~; 2015 by 2:00 p.m.-**new Bid Due Date April 7th, 2015**
2. See Attached asbestos sampling reports by HMS in regard to asbestos containing materials (ACM). All removal and disposal of related materials are to be handled accordingly as required for this project.
3. Revise sections 01 11 00 Summary of Work, 1.3, D 16 & Section 07 31 01, Part 1, 1.2, E. The Existing edge metal is to remain in place and be cleaned, primed and painted per section 09 91 00. Add to the scope of work painting of all outrigger/ beam covers to match the painted edge metal system as discussed at the pre bid meeting
4. Revise Section 07 31 01, Part 1, 1.2, F . Low profile dormer vents are to be installed at all buildings a minimum of 20' apart approximately 4' below the site screen.

Addendum must be signed, dated and returned with bid to confirm receipt and acknowledgement.

Signed _____

Date _____

Print Name _____

**MADERA UNIFIED
SCHOOL DISTRICT**
1902 Howard Road
Madera CA 93637
(559) 675-4500
(559) 675-1186 Fax
www.madera.k12.ca.us

Board of Trustees:

President:

Michael Salvador

Clerk:

Jose Rodriguez

Trustees:

Ricardo Arredondo

Lynn Cogdill


Robert Garibay

Ray G. Seibert

Maria Velarde-Garcia

SUPERINTENDENT:

Edward C. González



**Hazard
Management
Services**
SINCE 1984

FRESNO OFFICE * 371 E BULLARD AVENUE SUITE 109 * FRESNO CA 93710
PHONE (559) 436-0277 * FAX (559) 436-0279 * WWW.HAZMANAGE.COM

March 27, 2015

Mr. Curtis Manganaan
Director of Maintenance and Operations
Madera Unified School District
1902 Howard Road
Madera, CA 93637

Limited Asbestos Survey for Renovation Purposes
Berenda Elementary School
Multi-purpose Building and Classroom Building Re-roofing

Dear Mr. Manganaan:

This letter reports the results of the limited survey for asbestos-containing materials (ACM) performed on March 19, 2015, by Hazard Management Services, Inc. (HMS, Inc.) at the site referenced above. This survey was conducted at your request to identify asbestos-containing materials that may be disturbed by re-roofing of four structures at Berenda Elementary School. The structures include the multipurpose building and three classroom buildings. The survey conducted included and was limited to roofing materials on these structures.

The survey was performed by Josh Pyle, and supervised by Joe Vuglia, who are both accredited by the EPA to conduct building inspections for asbestos. There were several building materials observed which are considered "suspect" under US EPA guidelines. Under current US EPA guidelines for conducting building inspections for ACM, all "suspect" building materials must be **assumed** to contain asbestos until otherwise determined by laboratory testing. A list of suspect roofing materials that may be disturbed by the planned re-roofing, which were identified, sampled, and included in this survey, can be found in appendix A.

INSPECTION PROTOCOL

The following inspection process was followed by HMS, Inc. at the above referenced site:

The building roofs were accessible to the inspector.

The building roofs were visually inspected for suspect materials that may be disturbed by the planned re-roofing.

Representative bulk samples of each identified suspect material were collected using a scraper, chisel, or power drill. Sample locations are indicated on the bulk sample chain of custody form, and building diagram included with this report. The samples were analyzed using polarized light microscopy with dispersion staining (PLM) by Forensic Analytical in Hayward, CA, a NVLAP accredited laboratory.

If any materials other than those included in this report are discovered during the roof removal, it must be assumed that the materials contain asbestos and the project should then be halted and re-evaluated.

BULK SAMPLES

HMS, Inc. collected twenty-two (22) bulk samples of suspect materials identified on the roof of this structure. See the attached appendix and laboratory report for specific analysis information.



US EPA AND OSHA COMPLIANCE

US EPA

The US EPA NESHAP (40 CFR Part 61 - Nov. 20, 1990) requires materials containing greater than one percent asbestos be removed prior to renovation or demolition of a regulated building, if those materials are friable or likely to become friable due to the forces expected to act upon them during renovation or demolition. In California there are "delegated" counties which enforce the NESHAP regulations, and may have regulations more restrictive than the US EPA.

A 10 day waiting period is also required following demolition notification to the US EPA, regardless of the presence or absence of asbestos.

Division of Occupational Safety and Health (DOSH or Cal/OSHA)

Cal/OSHA worker health and safety regulations apply during any disturbance of ACM by a person while in the employ of another. This is true **regardless of friability or quantity disturbed**. If there is greater than 100 square feet of asbestos which will be affected by the demolition/renovation, a California Licensed Contractor who is registered with Cal/OSHA for asbestos is required. The regulations regarding asbestos are found in Title 8 CCR Section 1529, and also include formal notification requirements to Cal/OSHA at least 24 hours prior to removal.

Contractors State Licensing Board (CSLB)

Pursuant to current CSLB requirements, remediation contractors must carry each specific trade classification license for the materials and systems they will disturb, or carry the B General Contractor's license if they will disturb two or more trade areas. CSLB Asbestos certification is also required with either of these two options. The CSLB has recently added a third license option: effective January 1, 2015, contractors may obtain the C-22 asbestos abatement trade license in lieu of the former options. The C-22 license is an additional option for contractor compliance - it does not replace the previous framework. As noted above, DOSH registration for asbestos related work is required along with any of the CSLB licensing options.

DISCLAIMERS

The nature of renovation is such that materials can be uncovered which previously were unknown to exist. Therefore, HMS, Inc. cannot be responsible for "hidden materials", although every effort was made during the inspection to detect all suspect materials. If any materials other than those included herein are discovered during renovation or demolition, it must be assumed that the materials are asbestos-containing, and the project should then be halted and re-evaluated.

If you have any questions regarding this report, please contact our Fresno office at (559) 436-0277.

Sincerely,

A handwritten signature in black ink, appearing to read 'Joe Vuglia', written over a horizontal line.

Joe Vuglia, CAC 13-5005
Senior Project Manager
HMS, Inc. - Fresno

Appendix A

LIMITED ASBESTOS SURVEY FOR RENOVATION PURPOSES

BERENDA ELEMENTARY SCHOOL BUILDING 1 (MULTIPURPOSE), BUILDING 2-4 (CLASSROOM WINGS)

Survey Date: March 19, 2015

Report Date: March 27, 2015

BUILDING DESCRIPTION

The four subject structures at this site share a common construction and roofing history. The roof of each building consists primarily of composition shingles with tar and felt layers and a surface stone layer. Each building roof also has a central mechanical area separated by a screen wall. The mechanical area roofing consists of rolled composition roofing with a white sealant layer. Various mastics are present in the mechanical areas at seams and penetrations. Please refer to the attached sample location drawing for specific materials and sample locations.

BULK SAMPLE RESULTS

Suspect materials were identified on these roofs, and were sampled and analyzed. Where similar materials exist, they are assumed to be homogeneous and to have similar asbestos content. The following suspect materials were identified and sampled. Material samples were analyzed using polarized light microscopy (PLM) with dispersion staining to estimate the percent of asbestos.

Composition shingle roofing
Sealant layer (white)

Rolled composition roofing
Mastic (various)

RESULTS:


MATERIAL	LOCATION	ASBESTOS CONTENT	NESHAP CATEGORY
Mastic (black)	Buildings 1-4 mechanical areas, at penetrations*	2-5% Chrysotile	Category II, non-friable

*As noted in sampling record, asbestos-containing mastic may be concealed under white coating layer, in addition to mastic visible on the surface.

If any additional suspect materials are discovered during the re-roofing project and are not included in this survey, such materials must be assumed to contain asbestos and handled accordingly, or those materials should be sampled for laboratory analysis to determine asbestos content, and then handled accordingly.

Although not required under AHERA, this survey report should be kept with the management plan for this school site. Also, please include this complete report with contract documents and specifications related to the planned re-roofing of this structure. This report should also be included for permitting and notification in order to document compliance with the National Emissions Standard for Hazardous Air Pollutants (NESHAP) for asbestos for the San Joaquin Valley Air Pollution Control District (SJVAPCD).

Written by: Joe Vuglia, Cal/OSHA CAC 13-5005
Senior Project Manager
HMS, Inc. - Fresno





Bulk Asbestos Analysis

(EPA Method 600/R-93-116, Visual Area Estimation)

Hazard Mgmt. Services
Harry Stevens
Fresno Location
371 E. Bullard Ave., Ste. 109
Fresno, CA 93710

Client ID: 1636
Report Number: B203131
Date Received: 03/23/15
Date Analyzed: 03/24/15
Date Printed: 03/24/15
First Reported: 03/24/15

Job ID/Site: F15044 - Madera Unified SD, Berenda Elementary School**FALI Job ID:** 1636**Date(s) Collected:** 03/20/2015**Total Samples Submitted:** 22**Total Samples Analyzed:** 22

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
-----------	------------	---------------	------------------	---------------	------------------	---------------	------------------

HMS-MUSD-BES-F15044-01A

11622524

Layer: Stones	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Stones	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Black Felt	ND

Total Composite Values of Fibrous Components: **Asbestos (ND)**

Cellulose (25 %) Fibrous Glass (10 %)

Comment: Bulk complex sample.

HMS-MUSD-BES-F15044-01B

11622525

Layer: Stones	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Black Felt	ND

Total Composite Values of Fibrous Components: **Asbestos (ND)**

Cellulose (10 %) Fibrous Glass (20 %)

Comment: Bulk complex sample.

HMS-MUSD-BES-F15044-01C

11622526

Layer: Stones	ND
Layer: Black Tar	ND
Layer: Black Felt	ND
Layer: Black Felt	ND

Total Composite Values of Fibrous Components: **Asbestos (ND)**

Cellulose (50 %) Fibrous Glass (25 %)

Client Name: Hazard Mgmt. Services

Report Number: B203131

Date Printed: 03/24/15

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HMS-MUSD-BES-F15044-01D	11622527						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (50 %)	Fibrous Glass (25 %)						
HMS-MUSD-BES-F15044-01E	11622528						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (40 %)	Fibrous Glass (20 %)						
HMS-MUSD-BES-F15044-01F	11622529						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (40 %)	Fibrous Glass (20 %)						
HMS-MUSD-BES-F15044-01G	11622530						
Layer: Stones			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (40 %)	Fibrous Glass (20 %)						
HMS-MUSD-BES-F15044-02A	11622531						
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (20 %)	Fibrous Glass (25 %)						
Comment: Bulk complex sample.							

Client Name: Hazard Mgmt. Services

Report Number: B203131

Date Printed: 03/24/15

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HMS-MUSD-BES-F15044-02B	11622532						
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Layer: Black Tar			ND				
Layer: Black Felt			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (20 %) Fibrous Glass (25 %)							
Comment: Bulk complex sample.							
HMS-MUSD-BES-F15044-03A	11622533						
Layer: White Coating			ND				
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (7 %)							
HMS-MUSD-BES-F15044-03B	11622534						
Layer: White Coating			ND				
Layer: Black Mastic		Chrysotile	5 %				
Total Composite Values of Fibrous Components:		Asbestos (3%)					
Cellulose (7 %)							
HMS-MUSD-BES-F15044-04A	11622535						
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Fibrous Glass (2 %)							
HMS-MUSD-BES-F15044-05A	11622536						
Layer: Grey Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-06A	11622537						
Layer: Grey Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (15 %)							
HMS-MUSD-BES-F15044-07A	11622538						
Layer: White Non-Fibrous Material			ND				
Layer: Brown Non-Fibrous Material			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-08A	11622539						
Layer: Off-White Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
Cellulose (Trace)							

Client Name: Hazard Mgmt. Services

Report Number: B203131

Date Printed: 03/24/15

Sample ID	Lab Number	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer	Asbestos Type	Percent in Layer
HMS-MUSD-BES-F15044-09A	11622540						
Layer: Grey Mastic		Chrysotile	2 %				
Total Composite Values of Fibrous Components:		Asbestos (2%)					
HMS-MUSD-BES-F15044-10A	11622541						
Layer: Black Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-11A	11622542						
Layer: Grey Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-12A	11622543						
Layer: Grey Mastic			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-13A	11622544						
Layer: Black Mastic			ND				
Layer: White Coating			ND				
Total Composite Values of Fibrous Components:		Asbestos (ND)					
HMS-MUSD-BES-F15044-14A	11622545						
Layer: Grey Mastic		Chrysotile	5 %				
Total Composite Values of Fibrous Components:		Asbestos (5%)					



Tad Thrower, Laboratory Supervisor, Hayward Laboratory

Note: Limit of Quantification ('LOQ') = 1%. 'Trace' denotes the presence of asbestos below the LOQ. 'ND' = 'None Detected'.

Analytical results and reports are generated by Forensic Analytical Laboratories Inc. (FALI) at the request of and for the exclusive use of the person or entity (client) named on such report. Results, reports or copies of same will not be released by FALI to any third party without prior written request from client. This report applies only to the sample(s) tested. Supporting laboratory documentation is available upon request. This report must not be reproduced except in full, unless approved by FALI. The client is solely responsible for the use and interpretation of test results and reports requested from FALI. Forensic Analytical Laboratories Inc. is not able to assess the degree of hazard resulting from materials analyzed. FALI reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. All samples were received in acceptable condition unless otherwise noted.

BULK MATERIAL Analysis Request Form for Hazard Management Services, Inc.

P.O. BOX 576848
MODESTO, CA 95357-6848
(209) 551-2000
FAX (209) 551-2005

371 E. BULLARD AVE. STE 109
FRESNO, CA 93710
(559) 436-0277
FAX (559) 436-0279

2124 F STREET, #C
BAKERSFIELD, CA 93301
(881) 636-0351
FAX (881) 636-0361

☐ **Date:** March 20, 2015

Special Instructions: _____

☒ **Contact:** Harry Stevens

Bill: HMS, Inc.

Analysis Requested:

☒ **PLM with Dispersion Staining**

2 hr. ☒ 24 hr. 48 hr. Extended

AA Flame

TEM Bulk (5 Day)

Laboratory: FALI

Collected By: Josh Pyle

Date Collected: March 19, 2015

Job I.D.: F15044 - Madera Unified SD

Job Site: Berenda Elementary School

EMAIL RESULTS TO: hstevens@hazmanage.com & jpyle@hazmanage.com

SAMPLE #	RESULTS	MATERIAL DESCRIPTION/LOCATION
HMS-MUSD-BES-F15044 01A		Shingled roofing
		Building 1 (MPR); Roof; West end, South side near roof edge
HMS-MUSD-BES-F15044 01B		Shingled roofing
		Building 1 (MPR); Roof; North side, at center, West of roof peak
HMS-MUSD-BES-F15044 01C		Shingled roofing
		Building 2; Roof; East end, North side near roof edge
HMS-MUSD-BES-F15044 01D		Shingled roofing
		Building 2; Roof; West end, North side, East of ridge
HMS-MUSD-BES-F15044 01E		Shingled roofing
		Building 3; Roof; North side, at center, near roof edge
HMS-MUSD-BES-F15044 01F		Shingled roofing
		Building 3; Roof; East end, South of center, inside mechanical well, near ridge
HMS-MUSD-BES-F15044 01G		Shingled roofing
		Building 4; Roof; Southeast corner near roof edge and ridge
HMS-MUSD-BES-F15044 02A		Rolled composition roofing
		Building 1 (MPR); Roof; West end, North of center, inside mechanical well, near AC 3 unit
HMS-MUSD-BES-F15044 02B		Rolled composition roofing
		Building 3; Roof; At center, inside mechanical well, North of AC 5 unit
HMS-MUSD-BES-F15044 03A		Roof mastic (black) under white coating
		Building 2; Roof; At center, inside mechanical well, South of AC 6 unit

Submitted By: [Signature]

Date: 03/20/15

Received By: [Signature]

Date: 03-23-15A10:29 RCVD

BULK MATERIAL Analysis Request Form for Hazard Management Services, Inc.

P.O. BOX 576848
MODESTO, CA 95357-6848
(209) 551-2000
FAX (209) 551-2005

371 E. BULLARD AVE. STE 109
FRESNO, CA 93710
(559) 436-0277
FAX (559) 436-0279

2124 F STREET, #C
BAKERSFIELD, CA 93301
(661) 636-0351
FAX (661) 636-0361

☐ **Date:** March 20, 2015

Special Instructions: _____

☐ **Contact:** Harry Stevens

Bill: HMS, Inc.

Analysis Requested:

☒ **PLM with Dispersion Staining**

☐ **2 hr.** ☒ **24 hr.** ☐ **48 hr.** ☐ **Extended**

☐ **AA Flame**

☐ **TEM Bulk (5 Day)**

Laboratory: FALI

Collected By: Josh Pyle

Date Collected: March 19, 2015

Job I.D.: F15044 - Madera Unified SD

Job Site: Berenda Elementary School

EMAIL RESULTS TO: hstevens@hazmanage.com & jpyle@hazmanage.com

SAMPLE #	RESULTS	MATERIAL DESCRIPTION/LOCATION
HMS-MUSD-BES-F15044 03B		Roof mastic (black) under white coating
		Building 3; Roof; North side, West end, inside mechanical well, at exhaust hood
HMS-MUSD-BES-F15044 04A		Roof mastic (black)
		Building 1 (MPR); Roof; South side, West end, inside mechanical well
HMS-MUSD-BES-F15044 05A		Support mastic (grey)
		Building 1 (MPR); Roof; South side, at center, inside mechanical well
HMS-MUSD-BES-F15044 06A		Penetration mastic (black)
		Building 1 (MPR); Roof; West end, North of center, at KEF-1 unit
HMS-MUSD-BES-F15044 07A		Sealant (white)
		Building 1 (MPR); Roof; West end, North side, at exhaust fan
HMS-MUSD-BES-F15044 08A		Penetration mastic (grey)
		Building 1 (MPR); Roof; North side, at center, on roof peak
HMS-MUSD-BES-F15044 09A		Penetration mastic (black) 2
		Building 2; Roof; South side, East end, at exhaust fan
HMS-MUSD-BES-F15044 10A		Roof mastic (black) 2
		Building 2; Roof; East side, at center, inside mechanical well
HMS-MUSD-BES-F15044 11A		Penetration mastic
		Building 4; Roof; East end, South side, inside mechanical well
HMS-MUSD-BES-F15044 12A		Support mastic (grey) 2
		Building 4; Roof; North side, East end, inside mechanical well

Submitted By: John L. Pyle

Date: 03/20/15

Received By: [Signature]

Date: 03-23-15A10:29 RCVD

**P.O. BOX 57684B
MODESTO, CA 95357-6848
(209) 551-2000
FAX (209) 551-2005**

371 E. BULLARD AVE. STE 109
FRESNO, CA 93710
(559) 436-0277
FAX (559) 436-0279

**2124 F STREET, #C
BAKERSFIELD, CA 93301
(661) 636-0351
FAX (661) 636-0361**

Special Instructions:

Bill: HMS, Inc.

X PLM with Dispersion Staining

	2 hr.	X	24 hr.	48 hr.	Extended
1. <i>Staphylococcus aureus</i>	100	100	100	100	100
2. <i>Staphylococcus epidermidis</i>	100	100	100	100	100
3. <i>Staphylococcus saprophyticus</i>	100	100	100	100	100
4. <i>Staphylococcus sciuri</i>	100	100	100	100	100
5. <i>Staphylococcus carnosus</i>	100	100	100	100	100
6. <i>Staphylococcus hyacinthi</i>	100	100	100	100	100
7. <i>Staphylococcus saprophylus</i>	100	100	100	100	100
8. <i>Staphylococcus aureus</i>	100	100	100	100	100
9. <i>Staphylococcus aureus</i>	100	100	100	100	100
10. <i>Staphylococcus aureus</i>	100	100	100	100	100
11. <i>Staphylococcus aureus</i>	100	100	100	100	100
12. <i>Staphylococcus aureus</i>	100	100	100	100	100
13. <i>Staphylococcus aureus</i>	100	100	100	100	100
14. <i>Staphylococcus aureus</i>	100	100	100	100	100
15. <i>Staphylococcus aureus</i>	100	100	100	100	100
16. <i>Staphylococcus aureus</i>	100	100	100	100	100
17. <i>Staphylococcus aureus</i>	100	100	100	100	100
18. <i>Staphylococcus aureus</i>	100	100	100	100	100
19. <i>Staphylococcus aureus</i>	100	100	100	100	100
20. <i>Staphylococcus aureus</i>	100	100	100	100	100
21. <i>Staphylococcus aureus</i>	100	100	100	100	100
22. <i>Staphylococcus aureus</i>	100	100	100	100	100
23. <i>Staphylococcus aureus</i>	100	100	100	100	100
24. <i>Staphylococcus aureus</i>	100	100	100	100	100
25. <i>Staphylococcus aureus</i>	100	100	100	100	100
26. <i>Staphylococcus aureus</i>	100	100	100	100	100
27. <i>Staphylococcus aureus</i>	100	100	100	100	100
28. <i>Staphylococcus aureus</i>	100	100	100	100	100
29. <i>Staphylococcus aureus</i>	100	100	100	100	100
30. <i>Staphylococcus aureus</i>	100	100	100	100	100
31. <i>Staphylococcus aureus</i>	100	100	100	100	100
32. <i>Staphylococcus aureus</i>	100	100	100	100	100
33. <i>Staphylococcus aureus</i>	100	100	100	100	100
34. <i>Staphylococcus aureus</i>	100	100	100	100	100
35. <i>Staphylococcus aureus</i>	100	100	100	100	100
36. <i>Staphylococcus aureus</i>	100	100	100	100	100
37. <i>Staphylococcus aureus</i>	100	100	100	100	100
38. <i>Staphylococcus aureus</i>	100	100	100	100	100
39. <i>Staphylococcus aureus</i>	100	100	100	100	100
40. <i>Staphylococcus aureus</i>	100	100	100	100	100
41. <i>Staphylococcus aureus</i>	100	100	100	100	100
42. <i>Staphylococcus aureus</i>	100	100	100	100	100
43. <i>Staphylococcus aureus</i>	100	100	100	100	100
44. <i>Staphylococcus aureus</i>	100	100	100	100	100
45. <i>Staphylococcus aureus</i>	100	100	100	100	100
46. <i>Staphylococcus aureus</i>	100	100	100	100	100
47. <i>Staphylococcus aureus</i>	100	100	100	100	100
48. <i>Staphylococcus aureus</i>	100	100	100	100	100
49. <i>Staphylococcus aureus</i>	100	100	100	100	100
50. <i>Staphylococcus aureus</i>	100	100	100	100	100
51. <i>Staphylococcus aureus</i>	100	100	100	100	100
52. <i>Staphylococcus aureus</i>	100	100	100	100	100
53. <i>Staphylococcus aureus</i>	100	100	100	100	100
54. <i>Staphylococcus aureus</i>	100	100	100	100	100
55. <i>Staphylococcus aureus</i>	100	100	100	100	100
56. <i>Staphy</i>					

AA Flame

TEM Bulk (5 Day)

Laboratory: FALI

Collected By: Josh Pyle

Date Collected: March 19, 2015

Job I.D.: F15044 - Madera Unified SD

Job Site: Berenda Elementary School

EMAIL RESULTS TO: hstevens@hazmanage.com & jpyle@hazmanage.com

[illegible]

Submitted By: John E. Page

Date: 03/20/15

Received By: 

Date:

~~05-23-15A10:29~~ RCVD

