A. Location of Work

1. Berenda Elementary- THIS SITED HAS BEEN DELETED FROM THE SCOPE OF WORK

- a) Near the staff lounge: 1ea. staff men's restroom, 1 ea. staff women's restroom, 1ea. boys restroom, 1 ea. girls restroom
- b) Room 16: 1ea. boys restroom, Room 17: 1ea. girls restroom
- c) Room 28: 1ea. boys' restroom, Room 29: 1ea. girls restroom
- d) Cafeteria: 1ea. boys restroom, 1ea. girls restroom
- 2. Eastin-Arcola Elementary School
- a) 4 ea. 3 ea. Boys restrooms, 4 ea. 3 ea. Girls restrooms. Restrooms are located on the exterior ends of the classroom wings. Restroom by room 15 have been Deleted from the Scope of Work
- b) Add floor and base tile (only to the office staff men's and women's restrooms-This has been added to the Scope of Work

La Vina Elementary

- a) 2 ea. Boys restrooms, 2 ea. Girls restrooms. Restrooms are located on the exterior ends of the classroom wings.
- b) Staff workroom: 1ea. unisex restroom, Office: 1ea. unisex restroom Removed from the Scope of Work

B. Tile height on the walls:

- a) Berenda full height of the wall (approx. 8'-6"). Removed from the Scope of Work
- b) Eastin Arcola approx. 6'
- c) La Vina approx. 7' 6"