



# Laterals

\* All Dimensions to TOP of laterals and brackets

Steel Supplied by Others				
Part	Description	Size	Length	Quantity
A	Steel Columns	<b>DSA PC-90 04-122317</b>	32' 9-7/8"	3
B	Video Lateral	HSS 5" x 3" x 3/8"	23' 8-7/16"	3
C	Steel Base Plate	<b>DSA PC-90 04-122317</b>	N/A	3

Rev --

\*P1000 SL Strut preferred but P1000 T can be used



**DSA PC-90 04-122317**

See Sheet REF. FB2 for lateral hole locations

**Lateral Hole Orientations:**

All holes to be on top and bottom of laterals with holes shifted towards the front of the display

**Notes:**

1. Nevco provided hardware itemized on sheet with bolt/nut/screw bags.
2. Mark shortest column, then level across to others.
3. Provide a protective coating to minimize corrosion for all steel members exposed to weather, moisture, or soil.

**FOR REFERENCE ONLY**

Front View

Side View



Madera South High School Madera, CA Mechanical Installation			
Last ECO		Drawing No. Quote 43763 Mech	
Drawn JPW	Date 4/26/2024	Sheet of	

# Lateral Hole Locations


DSA PC-90 04-122317

Rev --

B - Video Lateral  
5" x 3" x 3/8" HSS



FOR  
REFERENCE  
ONLY

Madera South High School Madera, CA Mechanical Installation		 Nevco, Inc. Greenville, Illinois 62246	
Last ECO		Drawing No. Quote 43763 Mech	
Drawn JPW	Date 4/26/2024	Sheet of	